


Battery Replacement: Standard AES

Tools Required: None



Questions? Contact Guardian Alarm.

Your alarm system keypad display should now be clear of any low battery trouble. If the keypad is not clear, it is possible that the new battery is not at full charge. Allow 24 hours for full charge.

If you have any other questions, **please call 1.800.782.9688** and we'll be more than happy to help.